See also Survey for Theresa Malik 18" File

Eugene & Bertha Dupakoski
D. Vol. 395 Pg. 561

Clair R. & Mabel Rundle
D. Vol. 835 Pg. 100

Carl & Mae R. Krueger
D. Vol. 341 Pg. 427

Ollie E. & Ida K. Roberts Fd. No. 1 D. Vol. 839 Pg. 26

I.P. Fd. Reset off

21.11'

N. 89°01'W. 388.68' — I.P.Fd. — N. 88°52'W. 380.95' — I.P.Fd. — N.88°32'W. 165.00' — I.P.Fd. — 362.40' — N. 88°34'50"W. 413.12' — 1087.81' — 297.29' — 15.00' — 27.00' I.P.Fd. — 252.14' — I.P.Fd. — 270.13' — 30.01' I.P.Fd. — N. 88°34'50"W. Rev. 579.28'

R.R.S. Fd.

County I.P. in M.B. Pg. 1.64 South 0.03 East 8/17/82

310.05'

1033.29'

348.25'

379.99'

S.1°57'20"W.

O.L. 93

O.L. 88

409.65'

578.90'

S.1°05'W.

169.25'

O.L. 92

306.14

S. 88°34'50"E.

Robert & Karen M. Sobel
1193/508
2.500 Ac.

N.1°38'45"E. 359.69

N.1°42'15"E. 325.01' Rev.

34.55'

S. 88°35'15"E.

300.13

Robert & Karen M. Sobel
1197/857
2.000 Ac.

290.27 N.0°38'45"E.

324.83'

290.27 N.0°38'45"E.

90°46'

10' Utility Esmt.

300.13

288.30

288.30

288.30

N. 88°35'15"W.

33/30 & 31

See FA 24-Pg. 3 & 12" File

Marjorie G. Slansky
D. Vol. 1014 Pg. 154
See 12" File for 4 Parcel Split

℄ of County Ditch

650.00'

N. 2°50'30"E.

91°25'45"

27.00' I.P. Fd. Bent & Replaced — 282.27' — I.P.Fd. — 221.11' — 30.01' I.P.Fd. — N. 88°35'15"W. 560.39'

R.R.S. Fd.

2°50'30"
88°34'50"
91°25'45"

O.L. 88
O.L. 73

87.399 ACRES
REMAINING LAND

1096/650
Frank & Marilyn Y. Fetchet

959.23'

N. 2°50'30"E.

STATION ROAD 60'

N

169.25'

S.1°05'W.

320.38' — S.88°37'E. 462.83' — 677.20' — O.L. 88 O.L. 89 — 2039.44' — 579.03' — I.P.Fd. — S.89°19'15"E. 245.22' — 528.64' 253.40' 30.02'

AKINS RD. 60'

I.P.Fd. in Man Box

60' ROADWAY Established by Proceedings Recorded in Road Record Vol. 1 Pg. 357
Beginning at Northwesterly Corner of Original Lot 92 and extending Easterly along Lot Lines to (now) Columbia West River Road. Right-of-Way never used but no record found of any Vacation Proceedings.

PLAT OF SURVEY FOR
MILO H. STEARNS

ORIGINAL LOT 88 COLUMBIA TOWNSHIP
LORAIN COUNTY OHIO
SCALE: 1" = 100' MARCH 1972

See Field Book 26-Pg. 31

NOTE: ● indicates iron pin set unless otherwise designated.

Gary E. Penfound
Registered Surveyor No. 4457