03-00-037-101-032
03-00-037-A
4783

LAKE ERIE

Low Water Mark
Top of Bank
Top of Bank
14'
18'
5'
I.P.Set in shale
I.P.Set
I.P.Fd.
Tack in Step set
50.92
47.82
95.74 md.
90°
I.P.Set
I.P.Post Fd.
I.P.Set
56.0 md.
199.0 md.
2270 Rec.
127.78 md.
South
Due South
Stake Set
196' md.
225' Rec.
Due South
204.43 Rec.
188.5 md.
6
5
4
3
2
1
Block A
Block G.
I.P.Fd.
79.93 Rec.
79.40 md.
47'
I.P.Fd.
47'
47'
47'
188.00 Rec. & md.
72-29-30 Rec. & Md.
72-29-30 Rec.
47' Rec. in error
72-42-50 Rec.
N 0-13-20 W
Large Elm
I.P.Set
I.P.Fd.
47.20 obs
48.29 md
I.P.Fd.
47.00 Rec.
md.
I.P.Fd.
N 72-29-30 E
DRIVE
30'
PARK
I.P.Set
31.42
48.15 Rec.
I.P.Fd. 47' Rec.
Open Ditch
144.82 Rec.
7
8
47.57 Rec.
47' Rec.
I.P.
LAKE
N 72-29-30 E
ROAD
60'
31.42
523.20
31.42
HARRIS RD
N

Survey of sublots 5 & 6 Block A
In CORAL BEACH SUB'D. Vol. 11 Pgs. 17 & 18
In Part of Original Lot No. 37 Sheffield Twp.
Now in the Village of Sheffield Lake, Lorain Co. Ohio
For Dr. Roman Stetkevich
Scale:- 1" = 30' April 6, 1959
J. H. Getz, Reg. Engineer and Surveyor