09-00-068-000-010
09-00-078-000-
09-00-079-000
9-H
9-00-078-A
9-00-078-B
9-00-079-A

PPN 09-00-068-000-010
09-00-078-000-???
09-00-079-000-???

Map 25 9-H 9-00-078 A,B 09-00-079-A 44317

N

CENTRAL R.R. 66'

PENN

N.37°-25'-35"E. 2338.88

Francis P. Gerhartinger
8-4-49 D.V. 469 PG. 136

39.86'
I.P.Set
S.86°-41'-15"E. 255.71'
I.P.Set
S.89°-17'-15"E. 376.54'
I.P.Set
P.K.Spk.set in roof
S.1°-47'-10"W. 16.50'
S.89°-01'-10"E. 288.80
I.P.Set

1273.66'
S.1°-47'-10"W.

O.L. 68
O.L. 69
O.L. 78
O.L. 79

I.P.Set
S.88°-12'-50"E. 416.60'
I.P.Fd.

117.2979 Total acres

I.P.Fd.
41.18'
861.30'
N.89°-18'-25"W.
I.P.Set

N.1°-12'-25"E. 221.10'

I.P.Set
723.54'
N.89°-28'-20"W.
I.P.Set

N.1°-12'-25"E. 1234.00'

Monroe M. Vincent
2-1-34 D.V. 269 PG. 423

Mary Upham
7-13-37 D.V. 287 Pg. 140

1901.50'
S.1°-20'-28"W.

City of Oberlin
4-14-1903 D.V. 89 Pg. 447
4-24-52 D.V. 541 Pg. 93

24' San. Sewer?

I.P.Fd.
225.38'
N.88°-45'W.
I.P.Fd.

N.89°-40'-05"W. 40.00'
I.P.Set
I.P.Set
87.83
I.P.Set
631.97' N.89°-40'-05"W.
I.P.Set
I.P.Set 310.00'
I.P.Set

423.69'
S.18°-24'-20"W.

Grafton Lumber and Concrete Co.
4-23-65 D.V. 748 Pg. 634

N.1°-12'-25"E.
533.00'
N.1°-15'E.
330.00'
S.1°-15'W.

I.P.Fd.

Ignacio P. & Lucila B. Echeogaray
4-23-65 D.V. 907 Pg. 809

24" San. Sewer

24" San. Sewer

I.P.Set
I.P.Fd.
95.0'
30'
N.89°-40'-05"W.

STATE ROUTE 10 (EAST LORAIN ST.)

Survey for Brotherton Disposal Division of Browning Ferris Industries of Ohio Inc.
Part of O.L.'s. 68, 78 & 79 Russia Township
County of Lorain State of Ohio
Scale 1" = 200' August, 1975
Laundon · Simon · Cohl & Assoc. Inc.
Engineers Surveyors

Job No. 75-405 F.B. 177 Pgs. 29-30

59