

05-00-010-102- 032  
 ACRES CORRECTION PER. DEED VOL. 1307/521  
 SURVEYED BY : J.M. MARDEN JULY 29,46  
 deed incomplete. part of bearing missing  
 on deed. BEARING WAS ASSUMED TO RUN FOR

CLOSURE  $\frac{2 \times 12'E}{C=1:INF.}$

02'E	450.28	81.40	71	70	70	70	86.70	80	100	150
	132	132	132	150	150	150	150	150	150	150
	-039	-046	-037	-036	-034	-033	-032	-031	-030	
	.23A	.25A	.22A	.24A	.24A	.24A	.25A	.27A		
	75	82.56	71	70	70	70	86.70	80	100	150
SOUTH HAMHERST 5.00 + E.S. Line 0.110										

ELM SEE ST

5-00-011-

20-117700C TMDMRCO

2/9/89  
 #18260 A

APPROVED
LORAIN CO.
MAP DEPT.
DATE 12-28-88
PAGE 5-00-010-B
BY Carol Francis
VOID AFTER #18260 A