



SEE 5-00-059-A

ADD TO DUP.

COMM. RES  
65-776

PER DY. 530 PGS 349 & 355

10/12/89  
#18336A

APPROVED LORAIN CO. MAP DEPT.	
DATE	8-2-89
PAGE	5-00-042-B
BY	CARL FRODUS
VOID AFTER	#18336A

ERROR ON DY. 530/355 LAST BEARING TURN AROUND, SHOULD BE N29°38'W,