



SEE 5-00-017-A MILAN AVENUE
 977.43 to E
 1240
 S 1-00W 60'

THIS MAP NEEDS TO BE REDRAWN. THESE PARCELS AND SOME OF THE SUBLOTS ARE DRAWN INCORRECTLY.

63.88 230.02
 -027 0.33A
 199.99
 N 89-00 W 230 230

-016
 0.37 A
 S 89° 00' E

11 -001

10 -002
 104

9 -003

8 -001

7 -002

1/8/93
 #20185

APPROVED
 LORAIN CO.
 MAP DEPT.
 DATE 12/18/92
 PAGE 5-00-004-B
 BY T. HOLLIST
 VOID AFTER 20185

-026
 35.00 A.
 -028
 34.67 A.

SURVEYED BY: KS ASSOCIATES
 CLOSURE: 1:228, 648
 PRIOR INSTR. VOL. 1225 Pg. 10

FRANK
 LOGET