



#21509

I.P. FD.
 THIS TO CERTIFY THAT CERTAIN CORRECTIONS NEED TO BE MADE TO THE PLAT OF
 JAYCOX ROAD SUBD. NO. 2 AS RECORDED IN VOL. 55, PAGES 27, 28 of LORAIN
 COUNTY PLAT RECORDS. CHORD DISTANCES . CURVE DATA FOR NO. 20 ON CURVE
 TABLE BEING REVISED: CHORD FROM 100.03 TO 100.20 LENGTH FROM 102.03 TO 104.03
 ACREAGES TABULATION SHEET NO. 2 FROM 0.3293 TO 0.3294 R/W
 FROM 0.7131 TO 0.7132 SUB.

THE NUMBER 100.03 APPEARING ON R/W LINE OMITTE
 THE NUMBER 52.09 APPEARING ON R/W LINE OF REDWOOD BLVD SW. CORNER
 OF SUBLOT 16 omitt.
 AREA OF SUBLOT NO. 16 CHANGE FROM 16.720 TO 16.719 SF.

Closure 0.07:10,000
 P.P. NO. 04-00-019-143-446
 FRONTAGE Change From 179.73 X 199.42
 To 181.13 X 199.42

#21509-X
 APPROVED
 LORAIN CO.
 MAP DEPT
 DATE 3-14-96
 PLAT
 PAGE V.55/28
 BY CAROLYN
 FRANCIS
 # 21509-X

CORR TO JAYCOX ROAD SUB. NO 2

AREA IN 1 SUBLOT	0.3838
AREA IN RIGHT-OF-WAY	0.3294 0.3293
TOTAL AREA IN SUBDIVISION	0.7131 0.7132

61
138