

OHIO TURNPIKE

60'

ROAD 319.55' R.F.U.

MADDOCK 5-0° 28' 49" - E

Spike Found.

1450.51 M.

I.P.F.I.

P.K. Nail Set

319.55' R.F.U.

5-0° 28' 49" - E

48.05' R.F.M. N-87° 00' 51" - E

1" Rod Fd.

S-84° 08' 10" - W

(07-00-027-109-023) 1.83 AC. REC. 1.7935 AC. CALC.

P. & K. EXCAVATING COMPANY D.V. 1112 P. 618

S-55° 51' 50" - E

R/W FENCE 263.80' R.F.U.

Re-Bar Set

55.54' R.F.U.

S-84° 08' 10" - W

Re-Bar Set

142.84' R.F.U.

N-4° 20' 48" - E

S-89° 39' 09" - E 53.00' R.F.U.

Re-Bar Set

Re-Bar Set

15' CONC. SLAB ENCROACH.

24" DITCH

(07-00-027-109-024)

JOHN B. & IVAH M. KINTER

D.V. 783 P. 737

98.10' R.F.U. N-8° 50' 47" - E GRAVEL DRIVE

Re-Bar Set

Re-Bar Set

TRAILER

ENCROACHMENT 6'±

Re-Bar Set

64.70' R.F.U. N-50° 18' 46" - E

3/4" I.P.F.I.

158.53' R.F.U. N-60° 00' 47" - E



NORTH

BOUNDARY SURVEY

OF PART OF RIDGEVILLE TOWNSHIP ORIG. LOT 27 CITY OF NORTH RIDGEVILLE COUNTY OF LORAIN

STATE OF OHIO

SCALE: 1" = 40'

NOV. 17, 1994

PREPARED BY KS ASSOCIATES INC. ENGINEERS SURVEYORS

David L. Elwell REG. SURV. NO. 6333

