Lorain County Auditor's Office Geodetic Survey Marker

Alias: None

Township: Columbia

Horizontal Order: First

Vertical Order: Second

Set By: KS Associates, Inc.

Longitude: 81-57-14.66739

East (x) Meters: 645727.175

East (x) USFeet: 2118523.241

Survey By: KS Associates, Inc.

Station Name: 2005-65

USGS Quad: West View

Type of Mark: Bronze Disk Stamping on Mark: 2005-65

Horizontal Datum: NAD83(NSRS2007)

Latitude: 41-17-22.64475 North (y) Meters: 180366.947 North (y) USFeet: 591753.893

Convergence: 0-21-31.13 Combined Scale Factor: 0.99991275

State Plane Coordinate System Zone: Ohio North (3401)

Vertical Datum: NAVD88 Elevation (z) Meters: 249.966

Elevation (z) Meters: 249.966 Elevation (z) USFeet: 820.10 Location: The station is located at the Southeast corner of the intersection

of Station Road and Akins Road in Columbia Township. The station

is a bronze disk in concrete.

Readjusted March 2007

Method: GPS

