

This is To Corrected
Split No. ~~11785~~
11785
11786

#13947

11785
11786

H I

1126.28

W

7-044
2.58F.

#13947

6-045
2.57F.

1127.20

900

5 -068
2.07A.

-069
0.52A

227.20

227.20

-069

228.11

900

4 -070
1.90A.

-071
0.69A.

300

500

-071

0.69A.

Deed Vol 1209 P 627

1129.03

829.03

340

S O N T H
R I D G W

1129.95

2 -048
9.50F.

1130.87

T.M. 4.20.81
#13947

APPROVED
LOAN NO.
MAP DEPT.
DATE 11-26-85
PAGE 7-00-007- 1
BY <i>Carlyle S. Thomas</i>
VOID AFTER 13947

MAP CORRECTION ONLY

1132.40
N. 89 2'10"W

SEE 7-00-008-A

167.33

100

64.25

75
35

100

100.01

20

1125.36

825.36

300

20