

101

152
118

-006
1.29A.

1516.40
2001.12

475.50

-010
9.49A.

06-24-043-101- & 06-24-048-000-
SURVEYED BY: MICHAEL G. HURA REG. SURV.
PRIOR INST. 1314/763 (1) (3) (4)C=1:1000000.
(2)C=1:500000.

43

2033.40

④

Pt. -017
Pt. 5.60A

Pt. -017
Pt. 5.60A

④ ←2033.40→

←2031.59

←2031.59→

③

Pt. -016
Pt. 5.59A

Pt. -016
Pt. 5.59A

③

←2029.78

←2029.78→

①

Pt. -014
Pt. 6.16A

Pt. -014
Pt. 6.16A

①

←2027.77

←2027.77→

②

Pt. -015
Pt. 5.58A.

Pt. -015
Pt. 5.58A

2025.96

←2025.96→

←2025.96→

	0.L. 43 -009	0.L. 48 -012	4.20
SPLIT (1)	18.73A.	4.20 A	
	5.03A.	1.13 A.	
SPLIT (2)	13.70A.	3.07 A.	
	4.56A.	1.02 A.	
SPLIT (3)	9.14A.	2.05 A.	
	4.57A.	1.02 A.	
Rem (4)	4.67A.	1.03 A.	

#18614

APPROVED
LORAIN CO.
MAP DEPT.

DATE 9-~~2~~⁶-89

PAGE 6-57

BY CAROLYN
FRANCIS

VOID AFTER # 18614



2022.24

-008
9.36A.

SA 12/13/89
#18614

APPROVED
LORAIN CO.
MAP DEPT.

DATE 9-~~2~~⁶-89

PAGE 6-57

BY CAROLYN
FRANCIS

VOID AFTER # 18614



SEE 6-74

SEE 6-75

118
296.09
120
120
132.24
120
120
MURRAY RIDGE
296.12
60