

CURVE	LENGTH	RADIUS	DELTA	CHORD	CHORD BRG
C1	46.63	30.00	89°02'58"	42.07	N45°36'59"E
C2	47.62	30.00	90°57'02"	42.78	N44°23'01"W

JOHN H. GRITNER PLAT 7  
VOL. 11 PG. 20


West Park Road 50'

Jaycox Road (Width Varies)

WATERFORD ESTATES  
V. 59 P. 73

LEGEND

- Iron Pin Found
- Iron Pipe Found
- Iron Pin Set
- Ⓜ Monument Box Found
- Monument Box Empty
- ▲ PK Set
- △ PK Found
- ⊙ Stone Found
- Drill Hole Found
- ⊕ Drill Hole Set
- △ Horizontal Control Point
- Vertical Control Point
- ⊕ Hub Found
- ⊕ Hub Set
- ⊕ Railroad Spike Found
- ⊕ Railroad Spike Set
- Meas. = Measured
- Plot = Subdivision Plot
- D./M. = Deed & Measured
- Dd. = Deed
- Rec = Record
- Act. = Actual



I HEREBY CERTIFY THAT THIS PLAT WAS PREPARED FROM A FIELD SURVEY MADE UNDER MY DIRECT SUPERVISION IN NOVEMBER, 2001. MONUMENTS WERE FOUND OR SET AS INDICATED. DIMENSIONS ARE EXPRESSED IN FEET AND DECIMAL PARTS THEREOF. BEARINGS REFER TO THE CENTERLINE OF JAYCOX ROAD (N 1°05'30"E) PER INSTRUMENT #2001730278, FILM 1673 (BOARD OF PARK COMMISSIONERS). ALL OF WHICH ARE CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS PLAT WAS PREPARED IN ACCORDANCE WITH THE PROVISIONS OF CHAPTER 4733-37 IF THE OHIO ADMINISTRATIVE CODE.

RICHARD A. THOMPSON, JR., P.S.# 7388

No 01094  
APPROVED  
LORAIN CO.  
MAP DEPT  
DATE 6-13-02  
PAGE 4-00-014-D  
4-00-023-A-B  
BY J HATFIELD  
#02-01094

L.D.C. Inc. db.a. LAND DESIGN consultants  
Civil Engineers and Surveyors  
8585 EAST AVENUE • MENTOR, OHIO 44060  
TELEPHONE 255-8463 354-6936 951-1AND