



| CURVE TABLE | | | | | |
|-------------|--------|--------|-----------|-------|-------------|
| CURVE | LENGTH | RADIUS | DELTA | CHORD | CHORD BRG |
| C1 | 46.63 | 30.00 | 89°02'58" | 42.07 | N45°36'59"E |
| C2 | 47.62 | 30.00 | 90°57'02" | 42.78 | N44°23'01"W |

- LEGEND**
- Iron Pin Found
 - Iron Pipe Found
 - Iron Pin Set
 - Ⓜ Monument Box Found
 - Monument Box Empty
 - ▲ PK Set
 - △ PK Found
 - ⊙ Stone Found
 - ⊙ Drill Hole Found
 - ⊕ Drill Hole Set
 - △ Horizontal Control Point
 - ⊙ Vertical Control Point
 - ⊕ Hub Found
 - ⊕ Hub Set
 - ⊕ Railroad Spike Found
 - ⊕ Railroad Spike Set
 - Dd = Deed
 - Plot = Subdivision Plot
 - D./M. = Deed & Measured
 - Rec = Record
 - Act = Actual



I HEREBY CERTIFY THAT THIS PLAT WAS PREPARED FROM A FIELD SURVEY MADE UNDER MY DIRECT SUPERVISION IN NOVEMBER, 2001. MONUMENTS WERE FOUND OR SET AS INDICATED. DIMENSIONS ARE EXPRESSED IN FEET AND DECIMAL PARTS THEREOF. BEARINGS REFER TO THE CENTERLINE OF JAYCOX ROAD (N 1°05'30"E) PER INSTRUMENT #2001730278, FILM 1673 (BOARD OF PARK COMMISSIONERS). ALL OF WHICH ARE CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS PLAT WAS PREPARED IN ACCORDANCE WITH THE PROVISIONS OF CHAPTER 4733-37 IF THE OHIO ADMINISTRATIVE CODE.

RICHARD A. THOMPSON, JR., P.S.# 7388

LAND DESIGN consultants
 Civil Engineers and Surveyors
 8585 EAST AVENUE MENTOR, OHIO 44060
 TELEPHONE 235-8463 354-6938 951-LAND

Jaycox Road (Width Varies)

No 01140
 APPROVED
 LORAIN CO.
 MAP DEPT
 DATE 7-16-02
 PAGE 4-00-014-D
 BY JHaffield
 #02-01140

No 01139
 APPROVED
 LORAIN CO.
 MAP DEPT
 DATE 7-16-02
 PAGE 4-00-023-B
 BY JHaffield
 #01139