


NOTES: ● indicates iron pin set.
 ○ indicates iron pins found.
 ⊠ indicates iron pin found in monument box.

Correct Location of C.E. Penfound (Reg. Surv. #3200) Nov. 30-1970 Survey for Wilford Clement Reinders incorrectly described in D. Vol. 1022 Pg. 666.



PLAT OF SURVEY FOR WILFORD REINDERS
 PART OF LAND OF TWIN CREEK FARMS, INC.
 ORIGINAL SECTION NO. 17 CARLISLE TWP.
 LORAIN COUNTY OHIO
 SCALE: 1" = 100'
 Gary E. Penfound MARCH 19-1974
 Reg. Surveyor No. 4457