

Eaton Twp.

Grafton Twp.

IPF
1-1/4" pipe

1644.01' m

O.L. 8

-008
Pcl. 2

-008 & -011
Edward J. & Patricia A. Norris
V. 1361 P. 800

-011
Pcl. 1

3/4" IPF pipe

3/4" pipe
0.39' W
IPF


N89°49'14"E

1534.12' c.

1533.34' d.

IPF 1" pipe
24.76' c/l

15.2847 Ac.



IPS 30.00' c/l

N89°50'10"E

1535.81'

9.6988 Ac.

IPS 30.00' c/l

1537.45 d.

1536.88' m.

S89°50'10"W

3/4" pipe
IPF

433.97'
500°06'36"W 1267.43' m.
1269.65' d.

-003
Alan E. & Gayle L. Traxler
O.R. 1275 P. 412

IPF= Iron Pin Found
IPS=Iron Pin Set
Bearings are given to an assumed meridian and used to indicate angles only.
Basis of bearings is the bearing for the centerline of Island Road (N 0 deg 20' 00" W) as found in V. 1422 P. 983.

No 02013


APPROVED
LORAIN CO. PLAT DEPT

DATE 9-23-05

PAGE 16-D

BY JWH/Field

#05-02013



Plat of Survey
for

Mark & Dominique Saunders

Grafton Twp.
Lorain Co.

O.L. 8
Ohio

Carlson Surveys

August 2005

Island Rd. 60'

708.57' m. 709.26' d.
N00°20'00"E

433.57' c

275.00'

338.32' d&u

Aerial Control Monument

O.L. 8

MON

O.L. 13

GRAPHIC SCALE

1"=200'



0

200

400

600