



Point	Northing	Easting	Description
1	5000.00000	5000.00000	POINT
2	3952.33550	5128.94640	POINT
3	3884.15490	5127.31980	POINT
4	3901.53180	5980.59290	POINT
5	3885.07120	5172.31040	POINT
6	5020.51340	6007.28880	POINT
7	5000.00010	5000.00760	POINT
8	5000.61390	5030.14370	POINT
9	3885.09820	5173.64020	POINT
10	3892.99940	5561.61970	IRON PIN FOUND
11	5000.82280	5040.40160	point
12	4997.53510	4878.96510	point
13	5133.25700	4876.20110	IRON PIN FOUND
14	5134.10600	4917.89250	IRON PIN FOUND
15	5155.72240	5979.34240	point
16	5047.78130	5975.48500	point
17	5020.50750	6007.29600	REBAR FOUND
18	5155.72240	5979.33870	IRON PIN FOUND
19	5146.86450	5544.38310	IRON PIN FOUND
20	5000.90820	5039.68230	if bent reset
21	5000.80810	5039.68180	point
22	4207.59510	5256.32610	nail
23	3885.20470	5172.28290	IRON PIN FOUND
24	3905.97040	5107.54650	nail
25	3548.27120	5162.93590	nail
26	3634.48910	5752.17770	nail
27	3716.08930	5882.24150	nail
28	3892.09050	5976.68610	nail
29	3902.44150	5979.15220	IRON PIN FOUND
30	4086.78240	6022.40640	nail
31	4319.94870	5997.00900	nail
32	4533.88790	5940.21080	nail
33	4438.98410	5992.64730	REBAR FOUND
34	5020.52518	6007.28880	
35	4467.05829	5065.59438	Slide
36	4485.96205	5993.84345	Slide
37	4590.24179	5050.42291	
38	4467.67230	5095.74520	POINT
39	4214.21935	5230.62897	NAIL SET
40	3885.10984	5172.29562	IRON PIN FOUND
41	4613.92523	5135.11644	NAIL SET
42	4591.19740	5290.03704	NAIL SET
43	4594.64355	5266.79139	NAIL SET
44	4584.82729	5264.49734	BUILDING CORNER
45	4581.44483	5288.99916	BUILDING CORNER
46	4550.75730	5241.13302	BUILDING CORNER
47	4556.14201	5199.38512	BUILDING CORNER
48	4540.63509	5197.31010	BUILDING CORNER
49	4590.85587	5080.57665	POINT
50	4609.51789	5996.94260	POINT
51	4590.83262	5080.55192	REBAR SET
52	4574.08634	5511.33284	NAIL SET
53	4599.40523	5502.13128	REBAR SET
54	4590.68541	5743.56516	NAIL SET
55	4597.44949	5906.32834	NAIL SET
56	4609.53933	5996.95769	REBAR SET

Paul Heyslinger
32405 Brandon Road
Avon Lake, Ohio 44012
03-00-099-113-002
O.R. 0046, Pg. 756

Paul Heyslinger
32405 Brandon Road
Avon Lake, Ohio 44012
3-00-104-101-007
O.R. 0046 Pg. 0756

Church of St. Peter and Paul
Russian Orthodox
2238 East 32nd Street
Lorain, Ohio 44055
03-00-104-101-008
D.V. 687 Pg. 35

Church of St. Peter and Paul
Russian Orthodox
2238 E. 32nd Street
Lorain, Ohio 44055
03-00-104-101-009
D.V. 687 Pg. 35

Being known as part of Original Lots 99, 100, 104, and 105 of Sheffield Township now in the City of Lorain, County of Lorain, in the State of Ohio.

Note: Bearings shown are to an assumed meridian and are used to describe angles only.

Note: Only copies signed with Red Ink shall be considered Valid.
Patrick A. McGannon
Patrick A. McGannon P.S. 7154

Prepared for Mr. Jeff Barnes and St. Ladislaus Sick and Benefit Society of 4221 Clinton Avenue Lorain, Ohio, 44055.

#02689

APPROVED
LORAIN CO.
MAP DEPT

DATE 4-28-09

See Below
PAGE 300-104-A

BY JHA/H/LJ

099-02689

APPROVED BY THE LORAIN CITY PLANNING COMMISSION..... NO PLAT REQUIRED

03-00-104-101-001
03-00-099-113-001
03-00-105-105-001

Debbie
SECRETARY LORAIN CITY PLANNING COMMISSION

APPROVED
AS TO DESCRIPTION ONLY
Date 11-4-08
City of Lorain
Per *Jessica S. Polta*
Engineering Dept.

Boundary Survey

Patrick A. McGannon
Registered Professional Surveyor

1731 Gettysburg Drive, Lorain, Ohio 44053 (440)-2822712

