


NUM	DISTANCE	BEARING
L1	30.00'	S 1° 20' 15" W
L2	104.74'	S 50° 12' 16" E
L3	65.62'	S 88° 39' 45" E
L4	161.37'	N 67° 31' 42" E
L5	30.00'	N 1° 20' 15" E
L6	30.00'	S 1° 20' 15" W
L7	52.61'	S 79° 54' 59" E
L8	200.12'	S 86° 39' 29" E
L9	23.00'	S 1° 20' 15" W
L10	108.77'	S 88° 39' 45" E

09110
APPROVED
LORAIN CO. MAP DEPT
2013-13
JUL 21-E
BY JHATFIELD
#13-03110



Timothy Riley
Timothy Riley
Reg. Surveyor No. 6925



Timothy Riley
Engineer - Surveyor
Norwalk, Ohio

RR spike found
R/W Monument
Monument Box
Nail Set
9/16" hex bar set
Monument found
Inch Scale
E/C 1:10000

Plat of Survey
for
Steve Babcock

Twp. 2N, Rn 18W
Huntington Township
Tract 4
Lorain County

Revisions	
Ckd By:	TOR
Dwn By:	CAD
Date:	12-4-2012
Scale:	1" = 200'
Job No.	32016