

# Lorain County Auditor's Office

## Geodetic Survey Marker

Station Name: 2004-06  
USGS Quad: Grafton  
Type of Mark: Bronze Disk  
Stamping on Mark: 2004-06  
Horizontal Datum: NAD83(NSRS2007)  
Latitude: 41-19-44.09522  
North (y) Meters: 184667.903  
North (y) USFeet: 605864.612  
Convergence: 0-16-08.95  
State Plane Coordinate System Zone: Ohio North (3401)  
Vertical Datum: NAVD88  
Elevation (z) Meters: 231.129  
Location: To reach the monument, commence at the intersection of Butternut Ridge Road and Indian Hollow Road in Carlisle Township and travel North on Indian Hollow Road 0.4 miles more or less to the station on the right. The station is a bronze disk in concrete.

Alias: None  
Township: Carlisle  
Set By: KS Associates, Inc.  
Survey By: KS Associates, Inc.  
Horizontal Order: First Method: GPS  
Longitude: 82-05-25.07386  
East (x) Meters: 634296.543  
East (x) USFeet: 2081021.240  
Combined Scale Factor: 0.99991863  
Vertical Order: Second  
Elevation (z) USFeet: 758.30

Readjusted March 2007

