

# Lorain County Auditor's Office

## Geodetic Survey Marker

Station Name: 2006-43 USGS Quad: Grafton Type of Mark: Bronze Disk Stamping on Mark: 2006-43 Horizontal Datum: NAD83(NSRS2007) Latitude: 41-18-56.19381 North (y) Meters: 183177.263 North (y) USFeet: 600974.071 Convergence: 0-14-47.54 State Plane Coordinate System Zone: Ohio North (3401) Vertical Datum: NAVD88 Elevation (z) Meters: 231.224 Location: To reach the monument, commence at the intersection of Butternut Ridge Road and Lagrange Road in Carlisle Township and travel Southwest on Butternut Ridge Road 0.6 miles more or less to the station on the left. The station is a bronze disk in concrete.	Alias: None Township: Carlisle Set By: KS Associates, Inc. Survey By: KS Associates, Inc. Horizontal Order: First      Method: GPS Longitude: 82-07-29.00516 East (x) Meters: 631421.138 East (x) USFeet: 2071587.516 Combined Scale Factor: 0.99991759 Vertical Order: Second Elevation (z) USFeet: 758.61
--	---

