

Lorain County Auditor's Office

Geodetic Survey Marker

Station Name: 2006-46

USGS Quad: Grafton

Type of Mark: Bronze Disk

Stamping on Mark: 2006-46

Horizontal Datum: NAD83(NSRS2007)

Latitude: 41-19-25.52850

North (y) Meters: 184095.121

North (y) USFeet: 603985.410

Convergence: 0-16-08.76

State Plane Coordinate System Zone: Ohio North (3401)

Vertical Datum: NAVD88

Elevation (z) Meters: 236.372

Location: The station is located at the Northeast corner of the intersection of Butternut Ridge Road and Indian Hollow Road in Carlisle Township.

The station is a bronze disk in concrete.

Alias: None

Township: Carlisle

Set By: KS Associates, Inc.

Survey By: KS Associates, Inc.

Horizontal Order: First Method: GPS

Longitude: 82-05-25.37518

East (x) Meters: 634292.226

East (x) USFeet: 2081007.077

Combined Scale Factor: 0.99991740

Vertical Order: Second

Elevation (z) USFeet: 775.50

