

Lorain County Auditor's Office

Geodetic Survey Marker

Station Name: 2007-13

USGS Quad: Grafton

Type of Mark: Bronze Disk

Stamping on Mark: 2007-13

Horizontal Datum: NAD83(NSRS2007)

Latitude: 41-18-18.71693

North (y) Meters: 182035.163

North (y) USFeet: 597227.032

Convergence: 0-16-15.0

State Plane Coordinate System Zone: Ohio North (3401)

Vertical Datum: NAVD88

Elevation (z) Meters: 235.440

Location: To reach the monument, commence at the intersection of Indian Hollow Road and Slife Road in Carlisle Township and travel North on Indian Hollow Road 0.4 miles more or less to the station on the right. The station is a bronze disk in concrete.

Alias: None

Township: Carlisle

Set By: KS Associates, Inc.

Survey By: KS Associates, Inc.

Horizontal Order: First Method: GPS

Longitude: 82-05-15.79512

East (x) Meters: 634524.750

East (x) USFeet: 2081769.952

Combined Scale Factor: 0.99991621

Vertical Order: Second

Elevation (z) USFeet: 772.44

