

Lorain County Auditor's Office Geodetic Survey Marker

Station Name: 2007-14	Alias: None
USGS Quad: Grafton	Township: Carlisle
Type of Mark: Bronze Disk	Set By: KS Associates, Inc.
Stamping on Mark: 2007-14	Survey By: KS Associates, Inc.
Horizontal Datum: NAD83(NSRS2007)	Horizontal Order: First Method: GPS
Latitude: 41-18-00.49162	Longitude: 82-05-10.92712
North (y) Meters: 181473.486	East (x) Meters: 634640.652
North (y) USFeet: 595384.262	East (x) USFeet: 2082150.207
Convergence: 0-16-18.2	Combined Scale Factor: 0.99991567
State Plane Coordinate System Zone: Ohio North (3401)	
Vertical Datum: NAVD88	Vertical Order: Second
Elevation (z) Meters: 236.577	Elevation (z) USFeet: 776.17

Location: The station is located at the Southwest corner of the intersection of Indian Hollow Road and Slife Road in Carlisle Township. The station is a bronze disk in concrete.

